










Обработка профилей рам для продольного соединения при $L_{HP} > 6500$ мм


4110027 АУРС SL130 0180

4110027, 4110028 АУРС SL130 1980
4110028 АУРС SL130 1981АУРС SL130 0107
АУРС SL130 01084110027, 4110028 АУРС SL130 1980
АУРС SL130 1982


АУРС SL130 0110

АУРС SL130 0101
АУРС SL130 0102АУРС SL130 0103
АУРС SL130 0104



Обработка профиля для углового соединения методом штифтования






4110029




АУРС SL130 1983





АУРС SL130 0201




4110030




АУРС SL130 1984



4110031



АУРС SL130 0201



Провести указанную обработку как для АУРС SL130 0205, так и для собираемого с ним АУРС SL130 0201.