




Профиль створки		
АУРС.F50.1314		70
АУРС.F50.3.1315N	АУРС.F50.3.1315	82
АУРС.F50.3.1316N	АУРС.F50.3.1316	94
АУРС.F50.3.1317N	АУРС.F50.3.1317	106

Профиль створки		
АУРС.F50.1318		94 17.5
АУРС.F50.3.1319N	АУРС.F50.3.1319	106 17.5
АУРС.F50.3.1320N	АУРС.F50.3.1320	118 25
АУРС.F50.3.1321N	АУРС.F50.3.1321	130 25

Профиль створки		h	X
АУРС.F50 1322		131	17.5
АУРС.F50.3.1323N	АУРС.F50.3.1323	143	17.5
АУРС.F50.3.1324N	АУРС.F50.3.1324	155	25
АУРС.F50.3.1325N	АУРС.F50.3.1325	167	25

