

<table border="1"> <thead> <tr> <th colspan="2">Профиль створки</th> <th>h</th> </tr> </thead> <tbody> <tr> <td colspan="2">АУРС.F50.1314</td> <td>70</td> </tr> <tr> <td>АУРС.F50.3.1315N</td> <td>АУРС.F50.3.1315</td> <td>82</td> </tr> <tr> <td>АУРС.F50.3.1316N</td> <td>АУРС.F50.3.1316</td> <td>94</td> </tr> <tr> <td>АУРС.F50.3.1317N</td> <td>АУРС.F50.3.1317</td> <td>106</td> </tr> <tr> <td colspan="2">Подкладка под фрикц. ножницы</td> <td>кол-во</td> </tr> </tbody> </table>		Профиль створки		h	АУРС.F50.1314		70	АУРС.F50.3.1315N	АУРС.F50.3.1315	82	АУРС.F50.3.1316N	АУРС.F50.3.1316	94	АУРС.F50.3.1317N	АУРС.F50.3.1317	106	Подкладка под фрикц. ножницы		кол-во	<table border="1"> <thead> <tr> <th colspan="2">Профиль створки</th> <th>h</th> </tr> </thead> <tbody> <tr> <td colspan="2">АУРС.F50.1326</td> <td>86.2</td> </tr> <tr> <td>АУРС.F50.3.1327N</td> <td>АУРС.F50.3.1327</td> <td>98.2</td> </tr> <tr> <td>АУРС.F50.3.1328N</td> <td>АУРС.F50.3.1328</td> <td>110.2</td> </tr> <tr> <td>АУРС.F50.3.1329N</td> <td>АУРС.F50.3.1329</td> <td>122.2</td> </tr> <tr> <td colspan="2">Подкладка под фрикц. ножницы</td> <td>кол-во</td> </tr> </tbody> </table>		Профиль створки		h	АУРС.F50.1326		86.2	АУРС.F50.3.1327N	АУРС.F50.3.1327	98.2	АУРС.F50.3.1328N	АУРС.F50.3.1328	110.2	АУРС.F50.3.1329N	АУРС.F50.3.1329	122.2	Подкладка под фрикц. ножницы		кол-во
Профиль створки		h																																					
АУРС.F50.1314		70																																					
АУРС.F50.3.1315N	АУРС.F50.3.1315	82																																					
АУРС.F50.3.1316N	АУРС.F50.3.1316	94																																					
АУРС.F50.3.1317N	АУРС.F50.3.1317	106																																					
Подкладка под фрикц. ножницы		кол-во																																					
Профиль створки		h																																					
АУРС.F50.1326		86.2																																					
АУРС.F50.3.1327N	АУРС.F50.3.1327	98.2																																					
АУРС.F50.3.1328N	АУРС.F50.3.1328	110.2																																					
АУРС.F50.3.1329N	АУРС.F50.3.1329	122.2																																					
Подкладка под фрикц. ножницы		кол-во																																					
<table border="1"> <tr> <td>A 4060.07.55R</td> <td>8X D 4060.05.02</td> <td>8 шт.</td> </tr> <tr> <td>B 4060.08.55R</td> <td>8X D 4060.05.02</td> <td>8 шт.</td> </tr> </table>		A 4060.07.55R	8X D 4060.05.02	8 шт.	B 4060.08.55R	8X D 4060.05.02	8 шт.	<table border="1"> <tr> <td>A 4060.07.55R</td> <td>8X D 4060.05.02</td> <td>8 шт.</td> </tr> <tr> <td>B 4060.08.55R</td> <td>8X D 4060.05.02</td> <td>8 шт.</td> </tr> </table>		A 4060.07.55R	8X D 4060.05.02	8 шт.	B 4060.08.55R	8X D 4060.05.02	8 шт.																								
A 4060.07.55R	8X D 4060.05.02	8 шт.																																					
B 4060.08.55R	8X D 4060.05.02	8 шт.																																					
A 4060.07.55R	8X D 4060.05.02	8 шт.																																					
B 4060.08.55R	8X D 4060.05.02	8 шт.																																					
<p>H [мм] ↑</p> <table border="1"> <tr> <td>1600</td> <td> </td> <td> </td> </tr> <tr> <td>1401</td> <td> </td> <td> </td> </tr> <tr> <td>1400</td> <td> </td> <td> </td> </tr> <tr> <td>1201</td> <td> </td> <td> </td> </tr> <tr> <td>1200</td> <td> </td> <td> </td> </tr> <tr> <td>986</td> <td> </td> <td> </td> </tr> <tr> <td>985</td> <td> </td> <td> </td> </tr> <tr> <td>625</td> <td> </td> <td> </td> </tr> </table> <p>375 700 701 1400 1401 L [мм]</p>				1600			1401			1400			1201			1200			986			985			625														
1600																																							
1401																																							
1400																																							
1201																																							
1200																																							
986																																							
985																																							
625																																							
<table border="1"> <tr> <td>A 4060.07.55R</td> <td>B 4060.08.55R</td> <td>C 4060.09.55R</td> <td>D 4060.05.02</td> <td>E 4060.04</td> <td>F 4060.45</td> </tr> <tr> <td>G 4060.10.50</td> <td>H 4065.00</td> <td>I 4010.20</td> <td>J 1107.10R</td> <td>K 1107.10L</td> <td>L OS1</td> </tr> </table>		A 4060.07.55R	B 4060.08.55R	C 4060.09.55R	D 4060.05.02	E 4060.04	F 4060.45	G 4060.10.50	H 4065.00	I 4010.20	J 1107.10R	K 1107.10L	L OS1																										
A 4060.07.55R	B 4060.08.55R	C 4060.09.55R	D 4060.05.02	E 4060.04	F 4060.45																																		
G 4060.10.50	H 4065.00	I 4010.20	J 1107.10R	K 1107.10L	L OS1																																		