

		Профиль створки	h
		АУРС.F50.1313	51
		Подкладка под фрикц. ножницы	кол-во
	A 4060.07.55R	8X D 4060.05.02	8 шт.
	B 4060.08.55R	8X D 4060.05.02	8 шт.
	C 4060.09.55R	10X D 4060.05.02	10 шт.

H [мм] ↑	2200	<math>< 180 [кз]</math>	<math>< 180 [кз]</math>			
	1801					
	1800	<math>< 180 [кз]</math>	<math>< 180 [кз]</math>			
	1601					
	1600	<math>< 180 [кз]</math>	<math>< 180 [кз]</math>			
	1401					
	1400	<math>< 180 [кз]</math>	<math>< 180 [кз]</math>			
	1201					
	1200	<math>< 180 [кз]</math>	<math>< 180 [кз]</math>			
	971					
970	<math>< 180 [кз]</math>	<math>< 180 [кз]</math>				
611						
	360	700 701	1400	L [мм]		
	A 4060.07.55R	B 4060.08.55R	C 4060.09.55R	D 4060.05.02	E 4060.04	F 4060.45
	G 4060.10.50	H 4065.00	I 4010.20	J 1107.10R	K 1107.10L	L OS1