





Обработка профиля для углового соединения методом штифтования




АУРС W62 1981





PMW77.4

АУРС W62 0101,
АУРС W62 0102,
АУРС W62 0103


АУРС W62 1981





PMW77.4

АУРС W62 0121,
АУРС W62 0122,
АУРС W62 0123


АУРС W62 1980





PMW77.4

АУРС W62 0130,
АУРС W62 0131


АУРС W62 1980





PMW77.4

АУРС W62 0132,
АУРС W62 0133


АУРС W62 1987





PMW77.5

АУРС W62 0201,
АУРС W62 0221,
АУРС W62 0202,
АУРС W62 0222

АУРС W62 1987



PMW77.5

АУРС W62 0203,
АУРС W62 0223

Вариант 1. Обработка под экструдированную угловую закладную

Вариант 2. Обработка под литую угловую закладную